

**TECHNICAL DATA SHEET**

# CH4849

**Code 6100*****Super Stripping  
Approved Aircraft Paint Stripper  
Non-Phenolic, Neutral*****DESCRIPTION**

CH4849 is a powerful, neutral type, non-phenolic paint stripper for application by brush or spray onto aircraft surfaces.

**CHARACTERISTICS**

CH4849 is a non-phenolic, fast acting stripper. CH4849 is a heavy bodied, ammoniated, clear viscous material which will cling to vertical and inverted surfaces. CH4849 is non-corrosive and does not cause hydrogen embrittlement to aluminium, cadmium, high strength steel and all aircraft metal surfaces.

**APPROVALS**

CH4849 has been tested and qualified to :-

- Douglas CSD No. 1, Type III
- GPC-R-49 (RAAF TRS K55, DEF STAN 80-16)

CH4849 also conforms to :-

- USAF Mil-R-25134
- Boeing D6 17487
- AMS 1375

**APPLICATION**

**Precautions** - CH4849 is damaging to acrylics, most plastics and composites. Avoid contact to prevent damage. Clean any soiled or oily surfaces prior to stripping. Mask off all perspex, plastic or rubber components. To avoid unnecessary evaporation, carry out stripping operation away from direct sunlight or wind.

Apply CH4849 by spray or brush. For spraying use a President Hydra-Clean pump or equivalent. Once paint film has blistered, brush if necessary, and then rinse off with high pressure water, or scrape and rinse off with water.

As the stripper contains wax it is important to clean the surface firstly with an approved aircraft degreaser CH511C, CH087 or CH303MIL.

... /2

## TECHNICAL DATA SHEET

CH4849 (6100) - Page 2 of 2

### PACKAGING

4 Litre (4 per carton), 20 Litre, 200 Litre

### WARNING

Prolonged exposure to vapour is harmful to health. Forms dangerous gas near radiators or naked flames.

### FIRST AID

If poisoning occurs contact a doctor or Poisons Information Centre. If swallowed do not induce vomiting. Give a glass of water. Avoid giving milk oils and alcohol. If skin contact occurs remove contaminated clothing and wash skin thoroughly. Remove from contaminated area. Apply artificial respiration if not breathing. If in eyes, hold eyes open and flood with water for at least 15 minutes and see a doctor as soon as possible.

### SAFETY PRECAUTIONS

Avoid contact with the eyes, skin and avoid breathing vapour or spray mist. Do not smoke.

**WARRANTY** – All statements, information and data presented herein are believed to be accurate and reliable but are not to be taken as a guarantee, expressed or implied, for which seller assumes legal responsibility and they are offered solely for your consideration, investigation and verification. Statements or suggestions concerning possible use of this product are made without representation or warranty that any such use is free of patent infringement and are not recommendations to infringe on any patent.

Created 10 October 2008 Date Printed 28/03/2018 4:17 AM